

MetPrep Preparation Procedure – No 190



Electrical Contact – Brass – Silver/Nickel

	Surface	Abrasive	Pressure		Speed – Dir	Time
			Psi	N		
			Primary Grinding Stage	Paper		

	Surface	Abrasive	Pressure		Speed – Dir	Time
			Psi	N		
Additional Grinding Stages	Planocloth H	9 µm (WB) PCD Diamond	5	25	250 – Comp	5 mins
			5	25		
	Durasilk	3 µm (WB) PCD Diamond	5	25	250 – Comp	4 mins
	Durasilk	0.06µm Silco	5	25	100 – Comp	4 mins

	Surface	Abrasive	Pressure		Speed – Dir	Time
			Psi	N		
Polishing Stage	Multicloth	0.06µm Silco	3	15	80 – Comp	2 mins